

# Foamex Plant Fire

---

## Photo Log

---

Description: Preparing to make earthen berm on west side of site

Category:

Latitude:

Date Taken: 8/5/2005

Longitude:

Tags:



Description: Boom Location 1 at creek near Maybank Street and Lombardy Road

Category:

Latitude:

Date Taken: 8/5/2005

Longitude:

Tags:



Description: Closeup of burned material at facility

Category:

Latitude:

Date Taken: 8/5/2005

Longitude:

Tags:



Description: Dallas FD putting out hot spots at burned facility

Category:

Latitude:

Date Taken: 8/5/2005

Longitude:

Tags:

